

JET

DC-900A

DUST COLLECTOR

10001051MA

~230V, 50Hz

PARTS LIST

JPW (TOOL) AG

Tämperlistrasse 5

CH-8117 Fällanden

Switzerland

Phone +41 44 806 47 48

Fax +41 44 806 47 58


www.jettools.com



P-1000105MA

2015-12

Parts Breakdown for DC-900A Dust Collector



Parts List for DC-900A Dust Collector

Index No.	Part No.	Description	Size	Qty.
1	DC900A-001	Hex. Cap Nut	M8	4
2	DC900A-002	Caster	2"	4
3	DC900A-003	Base		1
4	DC900A-004	Socket Head Cap Screw	M5x8	12
5	DC900A-005	Collector Support		4
6	DC900A-006	Flat Washer	8	18
7	DC900A-007	Hex. Bolt	M8X10	6
8	DC900A-008	Collection Bag		1
9	DC900A-009	Cushion		2
10	DC900A-010	Collector		1
11	DC900A-011	Hex. Bolt	M8x45	4
12	DC900A-012	Handle		1
13	DC900A-013	Filter Bag		1
14	DC900A-014	Upper bag Support		1
15	DC900A-015	Switch	KJD12-230V	1
16	DC900A-016	Motor Complete Assembly	230V 50Hz 750W	1
	DC900A-016RC	Running Capacitor (not shown)	16µF±5%/450VAC	1
	DC900A-016-A	Junction Box		1
	DC900A-016-B	Junction Box Cover		1
	DC900A-016-C	Motor Fan (not shown)		1
	DC900A-016-D	Motor Cover		1
17	DC900A-017	Power Cord and Clamp		1
18	DC900A-018	Hex. Bolt	M8X25	4
19	DC900A-019	Hex. Bolt	M4X10	2
20	DC900A-020	Key	5x25	1
21	DC900A-021	Packing		1
22	DC900A-022	Fan housing		1
23	DC900A-023	Spring Washer	8	4
24	DC900A-024	Hex. Bolt	M8x16	4
25	DC900A-025	Cushion		2
26	DC900A-026	Impeller		1
27	DC900A-027	Packing		1
28	DC900A-028	Packing		1
29	DC900A-029	Washer		1
30	DC900A-030	Cap Screw (Left)	M6x20(Left)	1
31	DC900A-031	Inlet		1
32	DC900A-032	Nut	M8	4
33	DC900A-033	Bag clamp		2
34	DC900A-034	Wrench	10x8	1
35	DC900A-035	Manual & Part List		1
36	DC900A-036	Hex. Bolt	M6x10	6
37	DC900A-037	Pan Head Machine Screw	M4x10	4
38	DC900A-038	Ground wire		1
39	DC900A-039	Self-Tapping Screw	ST4.2x13	2
40	DC900A-040	Flat Washer	6	6
41	DC900A-041	Flat Washer	8	2
42	DC900A-042	Hose	Ø100x1500mm	1
43	DC900A-043	Hose Clamp	Ø100-115mm	2

Wiring Diagram for DC-900A Dust Collector

10001051MA ~230V, 50Hz

	colour of strands	Litzenfarben	couleur des cordons
BU	blue	blau	bleu
BN	brown	braun	brun
GNYE	green-yellow	grün-gelb	vert-jaune

	meaning of symbol	Bedeutung der Zeichen	interprétation
M	motor	Motor	moteur
S	switch	Schalter	interrupteur
C	condenser	Kondensator	condensateur

